

DAQ for Fall 2018 Run

T. Lindner


DAQ Task list for 2018 run

- New gate control
- Add timing of gate valves
- Clean up sequencer controls


- UCN Valve control (2017)
 - Open and close initiated by VME sequencer card.
 - Control signal converted from TTL to 24V and fed into PLC
 - Control signal copied and sent to Li-6 V1720

- Repeat for N more valves. Need

- Cables between VME crate and PLC.
- New PLC code and wiring.
- Don't have enough extra channels in V1720 digitizer to handle extra valve control signals.





- There aren't enough spare channels in V1720 to record signals from 4 more gate valves.
- Need to add some other card to record when the other valves open/close. Options:
 - MCS
 - Chronobox (used by ALPHA-G)
- Would other card be synchronized to same clock as V1720? Hopefully.
 - Otherwise injecting one gate signal into both V1720 and other card to synch them.
- We also will try to signal back from PLC that indicates exactly when the valves finish opening and closing. Could be useful to monitor that.
 - Need to think about how to implement that.





- Need to update the sequencer control page to add extra valves.
- How complicated, flexible to make the system for setting up valve sequences?
 - Possibly simple sequences get set through webpage and complicated sequences get set through scripts.
- Did we write up list of DAQ problems from last year? I will need some reminding of the bugs that we wanted to fix.
- Also need better online monitoring, so we catch these problems at the time...

- Problem with shifted hits is caused by missing the 17s clock roll-over on V1720 digitizer
- In case Steve noted (run 814) missed 8 clock roll-overs for second V1720 board.
- Possible to fix for 2017 data... but need to figure out how to automate the fix.
- For 2018 run, should investigate again whether we can get the new V1720 firmware working that has longer timestamps.



- Tried to avoid this problem by injecting a pulse-per-second signal into last channel of each V1720.
- But somehow this didn't work for second V1720 for this period.
 - possibly related to recalibrating V1720 baselines.
 - Somehow got fixed after Dec 1st, but can't find record of what was done.
- This problem is visible in history plots... need to add this to the hourly checks.
- Still not totally clear why the problem didn't affect all the runs in this period (Nov 29-31)





Kicker Sequence Module


Runs along west walkway!

Upper Mezzanine, B1U rack 5E

UCN Experimental Area

UCN Sequence in PPG:
 1) Wait XX seconds
 2) Open UCN valve, wait YY seconds, close UCN valve
 XX and YY are set through "Sequence Control" webpage

UCN PLC BOP
 Digital In Module
 UCN valve control 24V
 TTL->24V converter
 UCN Valve Control Signal
 TTL logic
 High = open valve



Notes

- V1720 connected by optical fibre to daq12
- PPG and V785 are controlled/readout through Ixdaq27 VME CPU
- NIM HV for He-3 not shown

Beam signal
 NIM logic
 High = on
 Low = off

High = beam off
 NIM logic
 Beam going off starts sequence

ADC Gate

Amplified Li-6 signal

He3 Signal)

Li-6 Signal (X9)

Amplified Li-6 Signal (X9)

High Voltage (X9)

He-3 UCN Detector

Li-6 UCN Detector

Logic signals

Analog signals