Contribution ID: 16 Type: Oral

Issues with extinguishing water piping systems at XFEL

Tuesday, 19 September 2017 10:00 (25 minutes)

DESY experienced issues with corroding extinguishing water piping systems recently installed for the European XFEL accelerator facility. These corrosions occurred just a couple of weeks after commissioning. Water and material samples were taken, analyses were made. Different measures to solve the issues were considered. What is the current status? How could a solution look like? What are the problems to deal with and the options to repair the piping while European XFEL is close to user operation?

Email

fabian.saretzki@desy.de

Funding Agency

Deutsches Elektronen-Synchrotron

Primary author: Mr SARETZKI, Fabian (DESY)

Presenter: Mr SARETZKI, Fabian (DESY)

Track Classification: Incident investigation and Lessons learned